

Resurvey of Sixth Standard Parallel South through R. 1 E.

CHAINS

A fir, 16 ins. diam., bears N. $60\frac{1}{2}^*$ W., 113 lks. dist., mkd. T27S R1E S32 SC BT.

Land, mountainous.

Soil, loose, coarse, rocky loam; 3rd and 4th fate.

Timber, fir, pine, cedar and hemlock.

Undergrowth, vine maple, rhododendron and chinquapin.

East, on S. bdy. of sec. 33.

Desc. broken SE. slope over cliffs and slide rock; through heavy green timber and dense undergrowth.

9.90 Spur, slopes SE.; desc. broken SE. slope.

19.60 Branch, 5 lks. wide, course S.; 350 ft. below the standard sec. cor.; asc. SW. slope.

75.22 The old cor. established for standard $\frac{1}{4}$ cor. of sec. 33, bears South, 113 lks. dist.

I destroy all evidence of this cor.

40.00 545 ft. above branch; spur, slopes S.

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for standard $\frac{1}{4}$ sec. cor., with brass cap mkd.

SC
 $\frac{1}{4}$ S33

1927

from which

A fir, 14 ins. diam., bears N. $52\frac{1}{2}^*$ E., 34 lks. dist. mkd. $\frac{1}{4}$ S33 SC BT.

A fir, 48 ins. diam., bears N. $68\frac{1}{2}^*$ W., 47 lks. dist., mkd. $\frac{1}{4}$ S33 SC BT.

Desc. 355 ft. over SE. slope.

50.60 Ravine, course SE., asc. 45 ft. over SW. slope.

55.35 Spur, slopes SE.; desc. 195 ft. over SE. slope.

60.25 Branch, 3 lks. wide, course SE.; asc. 25 ft. over SW. slope.

62.60 Point of spur, slopes S.; desc. 25 ft. over SE. slope.

65.05 Ravine, course SW.; asc. 70 ft. over SW. slope.