

County Surveyor's Record, Douglas County, Oregon

Resurvey of the Sixth Standard Parallel South through R. 1 E.

CHAINS

- 67.70 Point of spur, slopes S.; desc. 45 ft. over SE. slope.
- 69.50 Branch, 2 lks. wide, course S.; asc. 275 ft. over SW. slope, to spur.
- 74.47 The old cor. established for ~~standard~~ cor. of secs. 33 and 34, bears S.  $13\frac{1}{2}^*$  W., 172 lks. dist.  
I destroy all evidence of this cor.
- 76.65 Spur, slopes S.; desc. 55 ft. over SE. slope.
- 80.00 Set an iron post, 3 ft. long, 2 ins. diam., 29 ins. in the ground, for standard cor. of secs. 33 and 34, with brass cap mkd.

S	C
T27S	R1E
S33	S34

1927

from which

A hemlock, 22 ins. diam., bears N.  $52\frac{1}{2}^*$  E., 37 lks. dist., mkd. T27S R1E S34 SC BT.

A fir, 20 ins. diam., bears N.  $69\frac{1}{2}^*$  W., 27 lks. dist., mkd. T27S R1E S33 SC BT.

Land , mountainous.

Soil, loose, coarse, rocky loam; 3rd and 4th rate.

Undergrowth, vine maple, rhododendron and chinquapin.

Timber, fir, pine, cedar and hemlock.

East, on S. bdy. of sec. 34.

Desc. 90 ft. over SE. slope; through heavy green timber and dense undergrowth.

- 2.45 Branch, 2 lks. wide, course S.; asc. 115 ft. over SW. slope.

12.00 Spur, slopes S.; desc. 35 ft. over SE. slope.

- 14.50 Branch, 3 lks. wide, course SW.; asc. 590 ft. over W. slope to spur.

- 32.99 The old cor. established for standard  $\frac{1}{4}$  cor. of sec. 34, bears S.  $19-3/4^*$  W., 63 lks. dist.