

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 28 S., R. 1 E.

CHAINS

dist., mkd.  $\frac{1}{4}$  S25 BT.

Asc. 645 ft. over broken SE. slope.

65.50 Spur, slopes S.; desc. 215 ft. over SW. slope.

80.00 The cor. of secs. 23, 24, 25 and 26.

Land, mountainous.

Soil, loose, coarse, rocky loam; 3rd rate.


Timber, fir, pine and cedar.

~~Undergrowth, vine maple, rhododendron and laurel.~~

N. 0° 1' W., bet. secs. 23 and 24.

Asc. 590 ft. over SW. slope; through heavy green timber and dense undergrowth.

40.00 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap, mkd.



from which

A cedar, 30 ins. diam., bears N. 18° E., 55 lks.  
dist., mkd.  $\frac{1}{4}$  S24 BT.


A fir, 24 ins. diam., bears N. 10° W., 13 lks.  
dist., mkd.  $\frac{1}{4}$  S23 BT.

Asc. 130 ft. over SW. slope.

43.20 Spur, slopes SE.; desc. 355 ft. over NE. slope.

71.60 Ravine, course E., asc. 315 ft. over SE. slope.

80.00 Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for cor. of secs. 13, 14, 23 and 24, with brass cap mkd.



from which

A fir, 26 ins. diam., bears N. 45° E., 33 lks.  
dist., mkd. T28S R1E S13 BT.

A fir, 7 ins. diam., bears S.60° E., 31 lks.  
dist., mkd. T28S R1E S24 BT.