

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 28 S., R. 1 E.

CHAINS

A fir, 7 ins. diam., bears S. 77* W., 40 lks.
dist., mkd. T28S R1E S23 BT.

A fir, 16 ins. diam., bears N. 47 $\frac{1}{2}$ * W., 69 lks.
dist., mkd. T28S R1E S14 BT.

Land, mountainous.

Soil, loose, coarse, rocky loam; 3rd rate.

Timber, fir, pine, and cedar.

Undergrowth, vine maple and rhododendron.

N. 89* 50' E., on a random line bet. secs. 13 and 24.

40.00 Set temp. $\frac{1}{4}$ sec. cor.

80.02 Intersect E. bdy. of Tp., at the cor. of secs. 13, 18,
19 and 24, previously described in field notes of
T 28 S., R 2 E., this group.

Thence

S. 89* 50' W., on a true line bet. secs. 13 and 24.
Desc. 935 ft. over NW. slope; through heavy green
timber and dense undergrowth.

26.25 Quartz Creek, 30 lks. wide, course S.; asc. 375 ft.
over NE* slope.

40.01 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in
the ground, for $\frac{1}{4}$ sec. cor., with brass cap, mkd.

S13

$\frac{1}{4}$ _____

S24
1927

from which

A fir, 8 ins. diam., bears N. 62* E., 35 lks.
dist., mkd. $\frac{1}{4}$ S13 BT.

A fir, 10 ins. diam., bears S. 54* E., 10 lks.
dist., mkd. $\frac{1}{4}$ S24 BT.

Asc. 700 ft. over NE. slope.

75.20 Spur, slopes SE.; asc. 5 ft. over SE. slope.

80.02 The cor. of secs. 13, 14, 23 and 24.

Land, mountainous.