

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 28 S., R. 1 E.

CHAINS

A fir, 40 ins. diam., bears N. 16\* E., 42 lks. dist., mkd.  $\frac{1}{4}$  S12 BT.

A hemlock, 16 ins. diam., bears S. 80\* E., 20 lks. dist., mkd.  $\frac{1}{4}$  S13 BT.

Asc. 635 ft. over NE. slope.

68.00 Spur, slopes N.; desc. 50 ft. over NW. slope.

72.50 Ravine, course N.; asc. 85 ft. over NE. slope.

80.40 The cor. of secs. 11, 12, 13 and 14.

Land, mountainous.

Soil, loose, coarse, rocky loam; 3rd rate.

Timber, pine, fir, cedar and hemlock.

Undergrowth, vine maple, rhododendron and chinquapin.

N. 0\* 1' W., bet. secs. 11 and 12.

Desc. 20 ft. over NE. slope; through heavy green timber and dense undergrowth.

1.70 Branch, 5 lks. wide, course E.; asc. 215 ft. over SE. slope.


15.40 Spur, slopes E.; desc. 15 ft. over NE. slope.

17.40 Ravine, course E.; asc. 195 ft. over SE. slope.

28.75 Spur, slopes E.; desc. 215 ft. over NE. slope.

34.00 Ravine, course E.; asc. 115 ft. over SE. slope.

40.00 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.



from which

A fir, 20 ins. diam., bears N. 87\* E., 21 lks. dist., mkd.  $\frac{1}{4}$  S12 BT.

A fir, 8 ins. diam., bears N. 26\* W., 52 lks. dist., mkd.  $\frac{1}{4}$  S11 BT.

Asc. 15 ft. over SE. slope.

42.00 Spur, slopes E.; desc. 395 ft. over NE. slope.