

## County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 28 S., R. 1 E.

CHAINS

$$\frac{1}{4} \frac{S1}{S12}$$

1927

from which

A cedar, 12 ins. diam., bears N. 34\* E., 7 lks. dist., mkd.  $\frac{1}{4}$  S1 BT.

A cedar, 8 ins. diam., bears S. 68\* E., 19 lks. dist., mkd.  $\frac{1}{4}$  S12 BT.

Desc. 20 ft. over NW. slope.

41.00 Branch, 15 lks. wide, course S. 20\* W.; asc. 60 ft. over SE. slope.

47.40 Spur, slopes SW.; desc. 190 ft. over SW. slope.

51.80 Quartz Creek, 30 lks. wide, course S.; asc. 630 ft. over NE. slope.

80.44 The cor. of secs. 1, 2, 11 and 12.

Land, mountainous.

Soil, loose, coarse, rocky loam; 3rd rate.

Timber, pine, fir, cedar and hemlock.

Undergrowth, vine maple, rhododendron and chinquapin.

---

N. 0\* 1' W., on a true line bet. secs. 1 and 2.

Desc. 155 ft. over rolling NE. slope; through heavy green timber and dense undergrowth.

14.70 Branch, 8 lks. wide, course S. 70\* E.; asc. 115 ft. over rolling SE. slope.

31.45 Spur, slopes E.; desc. 135 ft. over rolling NE. slope to the  $\frac{1}{4}$  sec. cor.

39.85 Spring branch, 5 lks. wide, course E.

40.00 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.

$$\frac{1}{4} \frac{S2 | S1}{1927}$$

from which

A hemlock, 6 ins. diam., bears N. 24\* E., 36 lks. dist., mkd.  $\frac{1}{4}$  S1 BT.