

Subdivision of T. 28 S., R. 1 E.

CHAINS

A pine, 30 ins. diam., bears N. 62\* W., 104 lks. dist., mkd. T28S R1E S22 BT.

Land, mountainous.

Soil, loose, coarse, rocky loam; 2nd and 3rd rate.

Timber, fir, pine and cedar.

Undergrowth, vine maple, arrowwood, hazel, laurel and chinquapin.

N. 89\* 43' E., on a random line bet. secs. 23 and 26.

40.00 Set temp.  $\frac{1}{4}$  sec. cor.

79.96 Intersect N. and S. line, 26 lks. N. of the cor. of secs. 23, 24, 25 and 26.

Thence

S. 89\* 54' W., on a true line bet. secs. 23 and 26.

Desc. SW. slope; through heavy green timber and dense undergrowth.

11.30 Spring branch, 1 lk. wide, course S.

16.55 Branch, 9 lks. wide, course S.; 235 ft. below the sec. cor.; asc. 645 ft. over broken SE. slope.

39.98 Spur, slopes SE.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.

S23  
 $\frac{1}{4}$  —————  
S26  
1927

from which

A fir, 12 ins. diam., bears N. 60\* E., 40 lks. dist., mkd.  $\frac{1}{4}$  S23 BT.

A cedar, 12 ins. diam., bears S. 52\* E., 78 lks. dist., mkd.  $\frac{1}{4}$  S26 BT.

Asc. 750 ft. over SE. slope.

62.85 Spur, slopes SE.; desc. 640 ft. over SW. slope.

79.96 The cor. of secs. 22, 23, 26 and 27.

Land, mountainous.