

6th Stan. Par. South through R.2 E., as surveyed
by Samuel C. Flint, Deputy Surveyor, under contract
No. 473, dated June 5, 1883.

CHAINS	
	East on S. bdy. of Sec. 31. Var. 18°30'E.
2.50	Summit of Hill
16.73	Springbranch, 2 lks. wide, course S.
32.50	Summit of ridge
40.00	Set post 44x4 ins. firmly in the ground for Stan.
	1/4 sec. cor. marked S.C. on N. and S. faces from
	which:
	A pine, 16 ins. diam., bears S.20°E., 55 lks. dist.
	marked S.C. 1/4 S B T
	A cedar, 24 ins. diam., bears N.4°E., 212 lks. dist.
	marked S C 1/4 S B T
44.50	Stream, 5 lks. wide, course S. E.
80.00	Set post 48 x 4 ins. firmly in the ground for Stan. cor.
	to secs. 31 and 32, marked S C T 27 S R 2 E on
	N S 32 on E. and S 31 on W. faces with 5 notches
	on E. and 1 on W. edges from which:
	A fir, 14 ins. diam., bears N.35°E., 95 lks. dist.
	marked T 27 S R 2 E S 32 B T
	A fir, 18 ins. diam., bears N.14°W., 116 lks. dist.
	marked T 27 S R 2 E S 31 B T
	A fir, 30 ins. diam., bears S.40°E., 21 lks. dist.
	marked S B T
	Last 1/2 mile is thru burnt and down timber-line
	very brushy with thick fir and cedar brush.
	Land 3rd. rate, Mountainous and rocky.
	<hr/>
	East on S. bdy. of Sec. 32 Va. 18°20'E.
32.25	Stream, 8 lks. wide, course SE.
40.00	Set post 44 x 4 ins. firmly in the ground for Stan. 1/4
	sec. cor. marked S. C. on N. and S. faces from which:
	A fir, 24 ins. diam., bears S.20°W., 30 lks. dist.
	marked S C 1/4 S B T
	A fir, 30 ins. diam., bears N.45°W., 6 lks dist.
	marked S C 1/4 S B T
74.80	Summit of Mountain
80.00	Set post 50 x 4 ins. firmly in the ground for Stan. cor.