

## County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 28 S., R. 2 E.

## CHAINS

- 40.25 Ravine, course SE., asc. 620 ft. over SE. slope.  
 76.40 Spur, slopes W., desc. 30 ft. over NW. slope.  
 80.00 Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in  
 the ground, for cor. of secs. 13, 14, 23 and 24,  
 with brass cap mkd.

T28S R2E	
S14	S13
S23	S24
1926	

from which:

A cedar, 10 ins. diam., bears N.54\*E., 47 lks.

dist., mkd. T 28 S R 2 E S 13 B T

A fir, 30 ins. diam., bears S.47\*E., 47 lks.

dist., mkd. T 28 S R 2 E S 24 B T

A fir, 20 ins. diam., bears S.52\*W., 27 lks.

dist., mkd. T 28S R 2 E S 23 B T

A pine, 38 ins. diam., bears N.40\*W., 12 lks.

dist., mkd.. T 28 S R 2 E S 14 B T

Land, mountainous.

Soil, loose, coarse, rocky loam; 3rd. rate.

Timber; fir, pine and cedar.

Undergrowth, vine maple, rhododendron and chinquapin.

South, 89\*51'E., on a random line bet. secs. 13 and 24.

- 40.00 Set temp.
- $\frac{1}{4}$
- sec. cor.

- 80.04 Intersect E. bdy. of Tp., 21 lks. S. of the cor. of
- 
- secs. 13, 18, 19 and 24, heretofore described.

Thence

West, on a true line bet. secs. 13 and 24.

Over broken N. slope; through heavy green timber  
and dense undergrowth.

- 20.00 Spur, slopes NW., desc. 40 ft. over broken SW. slope.  
 36.00 Ravine, course SE., asc. 100 ft. over SE. slope.  
 40.02 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in  
 the ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.