

County Surveyor's Record, Douglas County, Oregon

Township 28 South, Range 3 East.
Subdivision.

CHAINS	
	Asc. 750 ft. over broken SW. slope to sec. cor.
40.00	Point for $\frac{1}{4}$ sec. cor. falls on steep surface rock where it is impracticable to set a corner.
48.00	Leave surface rocks, bears E. and W., thence through very heavy timber.
80.00	Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, for cor. of secs. 8, 9, 16, and 17, with brass cap marked
	T 28 S R 3 E S 8 S 9 S 17 S 16 1929
	from which
	A fir, 36 ins. diam., bears N.48*E., 67 lks. dist. Marked T 28 S R 3 E S 9 B T.
	A fir, 56 ins. diam., bears S.52*E., 40 lks. dist. Marked T 28 S R 3 E S 16 B T.
	A fir, 4 ins. diam., bears S.78*W., 21 lks. dist. Marked T 28 S R 3 E S 17 B T.
	A fir, 60 ins. diam., bears N.62*W., 20 lks. dist. Marked T 28 S R 3 E S 8 B T.
	Land, mountainous.
	Soil, rocky and gravelly, 2nd to 4th rate.
	Timber, fir, pine, hemlock, and larch.
	Undergrowth, salal, huckleberry, small fir, pine, and hemlock.
	N.89*48'E., on a random line, bet. secs. 9 and 16.
40.00	Set temp. $\frac{1}{4}$ sec. cor.
80.04	Intersect N. and S. line, 12 lks. S. of the cor. of secs. 9, 10, 16, and 17.
	Thence
	S.89*43'W., on a true line.
	Desc. 105 ft. over broken SW. slope, through stunted timber and medium undergrowth.