

County Surveyor's Record, Douglas County, Oregon

19547

Township 28 South, Range 3 East.
Subdivision.

CHAINS	
	$\frac{1}{4} \frac{S\ 17}{S\ 20}$ 1929
	from which A fir, 20 ins. diam., bears S.27*E., 13 lks. dist. Marked $\frac{1}{4}$ S 20 B T. A fir, 12 ins. diam., bears N.79*W., 43 lks. dist. Marked $\frac{1}{4}$ S 17 B T. Desc. 700 ft. over broken NW. slope.
73.50	Castle Rock Creek, 26 lks. wide, course SW., asc. 25 ft. over SE. slope to
79.96	The cor. of secs. 17, 18, 19, and 20. Land, mountainous. Soil, gravelly and rocky, third rate. Timber, fir, pine, hemlock, larch, and cedar. Undergrowth, rhododendron, vine maple, willow, small fir, pine, and yew.
40.00	N.89*46'W., on a random line, bet. secs. 18 and 19. Set temp. $\frac{1}{4}$ sec. cor.
82.07	Intersect W. bdy. of Tp. 37 lks. N. of the cor. of secs. 13, 18, 19, and 24. Thence N.89*58'E., on a true line. Desc. 40 ft. over NE. slope, through heavy timber and dense undergrowth.
8.00	Draw, drains NE., asc. 20 ft. over W. slope.
9.25	Ridge, bears NE. and SW., desc. 490 ft. over SE. slope.
36.86	Creek, 3 lks. wide, course SE., asc. 30 ft. over SW. slope to
42.07	Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked
	$\frac{1}{4} \frac{S\ 18}{S\ 19}$ 1929