

76
County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 29 S., R. 1 E.

CHAINS

A yew, 6 ins. diam., bears N.47*E., 20 lks. dist.,

mkd. T 29 S R 1 E S 13 B T

A fir, 36 ins. diam., bears S.69*E., 39 lks. dist.,

mkd. T 29 S R 1 E S 24 B T

A hemlock, 12 ins. diam., bears S.73*W., 51 lks. dist.,

mkd. T 29 S R 1 E S 23 B T

A hemlock, 18 ins. diam., bears N.41*W., 16 lks. dist.,

mkd. T 29 S R 1 E S 14 B T

Land; mountainous.

Soil; stony and shaly clay loam, 2nd and 3rd rate.

Timber; fir, hemlock, cedar and pine.

Undergrowth; chinquapin, snowbrush, hazel, fir.

N.89*51'E., on a random line, bet. secs. 13 and 24.

40.00 Set temp. $\frac{1}{4}$ sec. cor.

80.30 Intersect E. Bdy. of the Tp., 21 lks. N. of the cor. of
secs. 13, 18, 19, and 24, heretofore described.

Thence

West, on a true line, bet. secs. 13 and 24.

Over mountainous land, through heavy timber and dense
undergrowth.

Asc. 10 ft. on NE. slope.

0.60 Spur, slopes NE.; desc. 375 ft. on NW. slope.

19.00 Foot of descent, at ravine, course N.

22.05 Buckeye Creek, 25 lks. wide, course SW.; thence over
creek bench.

31.50 Leave bench, bears NE. and SW.; asc. 25 ft. on SE.
slope.

33.00 Top of ascent; thence over S. slope.

40.15 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in
the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

$\frac{1}{4}$ $\frac{S\ 13}{S\ 24}$
1921

from which,