

112
County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 29 S., R. 1 E.

CHAINS

- 73.80 Creek, 10 lks. wide, course N.; asc. 320 ft. on E. slope, to
- 80.24 The cor. of secs. 17, 18, 19 and 20.
Land; mountainous.
Soil; stony clay loam, 2nd and 3rd rate.
Timber; fir, hemlock, cedar and pine.
Undergrowth; chinquapin, hazel, fir, vine maple.
-
- N.89°54'W., on a true line, bet. secs. 18 and 19.
Over mountainous land, through heavy timber and dense undergrowth.
Asc. 155 ft. on E. slope.
- 10.00 Top of ascent, on bench, nearly level.
- 22.75 Creek, 1 lk. wide, course N.; asc. 20 ft. on E. slope.
- 27.00 Ridge, bears NE. and SW.; desc. 60 ft. on NW. slope.
- 35.00 Foot of descent; thence over N. slope.
- 40.00 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked
- S 18
 $\frac{1}{4}$ ———
S 19
1921
- from which,
- A cedar, 18 ins. diam., bears N.66°E., 53 lks. dist., mkd. $\frac{1}{4}$ S 18 B T
- A pine, 40 ins. diam., bears S.39°E., 30 lks. dist., mkd. $\frac{1}{4}$ S 19 B T
- Asc. 45 ft. on NE. slope.
- 44.00 Top of ascent; thence over N. slope.
- 49.50 Begin descent, 500 ft. on NW. slope.
- 76.50 Creek, 6 lks. wide, course NW.; thence over river bottom, along foot of hill.
- 79.71 Intersect Willamette Meridian, 3.20 chs. S.0°12'W. of the $\frac{1}{4}$ sec. cor. on E. bdy. of sec. 24, T. 29 S.,