

County Surveyor's Record, ¹¹⁶ Douglas County, Oregon

Subdivisions of T. 29 S., R. 1 E.

CHAINS

Soil; stony clay loam, 2nd and 3rd rate.
 Timber; fir, pine, cedar, and hemlock.
 Undergrowth; vine maple, fir, chinquapin, hazel.

N.89*54'W., on a true line, bet. secs. 7 and 18.
 Over mountainous land, through heavy timber and dense undergrowth.

Desc. 100 ft. on SW. slope.

10.80 Ravine, course SE.; asc. 20 ft. on E. slope.

17.25 Enter nearly level bench, bears NW. and SE.

26.25 Creek, 1 lk. wide, course SE.; asc. 85 ft. on E. slope,
 to

40.00 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in
 the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked

$$\begin{array}{r} S 7 \\ \frac{1}{4} \text{---} \\ S 18 \\ 1921 \end{array}$$

from which

A fir, 10 ins. diam., bears N.63*E., 35 lks. dist.,
 mkd. $\frac{1}{4}$ S 7 B T

A cedar, 28 ins. diam., bears S.28*W., 28 lks. dist.,
 mkd. $\frac{1}{4}$ S 18 B T

Asc. 190 ft. on E. slope.

56.70 Ridge, bears N. and S.; desc. 250 ft. on SW. slope, to

79.44 Intersect Willamette Meridian, 3.45 chs. S.0*09'W.
 of the $\frac{1}{4}$ sec. cor. on E. bdy. of sec. 13, T. 29 S.,
 R. 1 W, and set closing cor., heretofore described.

Land; mountainous.

Soil; clay loam, stony in places, 2nd and 3rd rate.

Timber; fir, cedar, hemlock, and pine.

Undergrowth; chinquapin, hazel, fir, vine maple.