

27

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 29 S., R. 2 E.

## CHAINS

- 80.40 Intersect East bdy. of Tp. 12 lks. S. of the cor. of  
Secs. 19, 24, 25 and 30.
- Thence,  
N.89°50'W., on a true line bet. Secs. 24 and 25.  
Over mountainous land, through heavy timber and dense  
undergrowth.  
Ascend 80 ft. over SE. slope.
- 2.10 Spur, slopes S. Descend 30 ft.
- 5.36 Brook, 1 lk. wide, C. S. Ascend 85 ft. over E. slope.
- 7.76 Spur, slopes S. Descend 100 ft.
- 13.51 Brook, 5 lks. wide, C. SE. Ascend 355 ft. over SE.  
slope.
- 29.45 Spur, slopes S. Descend 320 ft. over W. slope to
- 40.20 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in  
the ground, for  $\frac{1}{4}$  Sec. cor. with brass cap marked
- S 24  
1/4 \_\_\_\_\_  
S 25  
1923
- from which
- A Fir, 20 ins. diam., bears N.87°E., 56 lks. dist.,  
marked  $\frac{1}{4}$  S 24 B T.
- A Fir, 20 ins. diam., bears S.13°E., 63 lks. dist.,  
marked  $\frac{1}{4}$  S 25 B T.
- 41.04 Creek, 5 lks. wide, C. S. Ascend 480 ft. over SE. slope.
- 62.15 Spur, slopes S. Descend 160 ft.
- 70.72 Brook, 1 lk. wide, C. S.
- 74.48 Brook, 1 lk. wide, C. SE. Ascend 120 ft. over E.  
slope to
- 80.40 The cor. of Secs. 23, 24, 25 and 26.  
Land, mountainous.  
Soil, clay loam and rocky; 2nd and 3rd rate.  
Timber, Fir, Cedar and Pine.  
Undergrowth, Fir and Rhododendron.