

74
County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 29.S., R. 2 E.

CHAINS	
	Over mountainous land, through heavy timber and dense undergrowth. Descend gradually, over SW. slope.
39.95	Set an iron post, 3 ft. long, 1 in. dia., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked $\frac{1}{4} \frac{S \ 20}{S \ 29}$ 1926 from which A fir, 30 ins. dia., bears N. 40* E., 16 lks. dist., marked $\frac{1}{4}$ S 20 BT. A cedar, 12 ins. dia., bears S. 25*W., 27 lks. dist., marked $\frac{1}{4}$ S 29 BT. Descend 300 ft., over W. slope.
66.54	Creek, 10 lks. wide, little water, course NW. Ascend 275 ft., over NE. slope.
75.50	Spur, slopes NW. Descend 130 ft., over SW. slope to
79.90	The cor. of secs. 19, 20, 29 and 30. Land, mountainous. Soil, clay loam; 2nd rate. Timber, fir, cedar, hemlock and madrona. Undergrowth, rhododendron, chinquapin, fir and madrona.

	West, on a random line, bet. secs. 19 and 30.
40.00	Set temp. $\frac{1}{4}$ sec. cor.
76.49	Intersect W. bdy. of Tp. 38 lks. S. of the cor. of secs. 19, 24, 25 and 30, which is a basalt stone, 6 x 5 x 4 ins. above ground, firmly set, marked and witnessed as described by the surveyor general. Thence, S. 89* 43' E., on a true line, bet. secs. 19 and 30. Over mountainous land, through heavy timber and medium undergrowth. Ascend 475 ft., over broken SW. slope.
26.50	Spur, slopes NW., ascend gradually along N. slope to
36.49	Set an iron post, 3 ft. long, 1 in. dia., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked