

Subdivision of T. 29 S., R. 2 E.

CHAINS

ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.

$\frac{1}{4}$  S 5  
S 8  
1926

from which

A hemlock, 5 ins; diam., bears N.  $12\frac{1}{2}^{\circ}$ E.,  $41\frac{1}{2}$  lks. dist., mkd.  $\frac{1}{4}$  S 5 B T

A Douglas fir, 14 ins. diam., bears S.  $53\frac{1}{2}^{\circ}$ W., 40 lks. dist., mkd.  $\frac{1}{4}$  S 8 B T

Ascend 180 ft., over NE. slope.

48.40 Spur, slopes NW. Descend 400 ft. to

79.60 The corner of secs. 5, 6, 7 and 8.

Land, mountainous.

Soil, clay loam and rocky; 2nd and 3rd rate.

Timber, fir, pine and cedar.

Undergrowth, rhododendron, dogwood, vinemaple and fir.

West, on a random line, bet. secs. 6 and 7.

40.00 Set temp.  $\frac{1}{4}$  sec. cor.

76.32 Intersect W. bdy. of Tp., 2 lks. S. of the cor. of secs. 1, 6, 7 and 12, which is an iron post, 2 ins. diam., 12 ins. above the ground, firmly set, marked and witnessed as described in notes of E. bdy. of T. 29 S., R. 1 E.

Thence,

S.  $89^{\circ}59'$ E., on a true line, bet. secs. 6 and 7.

Over heavily rolling summit land, through heavy timber and dense undergrowth.

Along gradual N. slope.

30.24 U.S. Location Monument for Homestead Entry Survey No. 192 a conglomerate stone, 10x15x6 ins. above ground, firmly set, marked and witnessed as described in the notes of said survey, bears South, 13.22 chs. dist.,

36.32 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.

$\frac{1}{4}$  S 6  
S 7  
1926

From which