

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 29 S., R. 3 E.

CHAINS

Thence

S.89*47'W., on a true line.

Over mountainous land, through medium timber and medium undergrowth.

Asc. 620 ft. over NE. slope.

30.00 Spur, slopes SE., desc. 50 ft. over SW. slope to

40.18 Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked
$$\begin{array}{r} \text{S } 26 \\ \frac{1}{4} \text{ S } 35 \\ 1927 \end{array}$$

From which

A Pine, 5 ins. in diam., bears N.25*E., 14 lks. dist., marked $\frac{1}{4}$ S 26 B T.

A Cedar, 40 ins. in diam., bears S.45*W., 27 lks., dist., marked $\frac{1}{4}$ S 35 B T.

This cor. is at the foot of desc. on S. slope, asc. 150 ft. over broken SE. slope.

44.75 Rock spur, slopes S., desc. 60 ft. over SW. slope.

46.25 Foot of desc. on S. slope, asc. 120 ft. over SE. slope.

49.00 Rock spur, slopes S., desc. 510 ft. over SW. slope

68.35 Creek, 8 lks. wide, course SE., asc. 255 ft. over NE. slope to

80.36 The cor. of secs. 26, 27, 34 & 35.

Land., Mountainous.

Soil., Sandy loam & rocky. 2nd & 4th rate.

Timber., Fir, pine & cedar.

Undergrowth., Vine maple, alder, huckleberry, snow brush, small fir, pine & yew.

N.0*02'W., bet. secs. 26 & 27.

Over mountainous land, through medium timber & medium undergrowth.

Desc. 145 ft. over N. slope.

11.50 Creek, 5 lks., wide, course, SE., asc. 620 ft. over S. slope, through grassy openings.