

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 29 S., R. 3 E.

CHAINS	East, on a random line bet. secs. 27 and 34.
40.00	Set temp. $\frac{1}{4}$ sec. cor.
80.22	Intersect N. and S. line 5 lks. S. of the cor. of secs. 26, 27, 34 and 35.
	Thence
	S. 89° 58' W., on a true line.
	Over mountainous land, through stunted timber and light undergrowth.
	Asc. 305 ft. over broken NE. slope.
0.02	E. side of line tree, a fir, 5 ft. in diam., marked with 2 notches on E. and W. sides.
16.20	Rock spur, slopes N., desc. 305 ft. over NW. slope, enter heavy timber, bears N. and S.
33.20	Creek, 8 lks. wide, course N., asc. 240 ft. over E. slope, leave heavy timber, bears N. and S., thence through scattering timber and open grassy spaces.
40.11	Set an iron post, 3 ft. long, 1 in. in diam., 30 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked
	$\frac{1}{4} \begin{array}{l} S 27 \\ S 34 \\ 1927 \end{array}$
	from which
	A Fir, 8 ins. in diam., bears N. 22° E., 21 lks. dist., marked $\frac{1}{4}$ S 27 B T.
	A Cedar, 30 ins. in diam., bears S. 23° E., 135 lks. dist., marked $\frac{1}{4}$ S 34 B T.
	Asc. 425 ft. over E. slope.
48.30	Forest Service Trail, bears N. and S.
53.00	Ridge, bears N. and S., desc. 470 ft. over W. and NW. slope to
80.22	The cor. of secs. 27, 28, 33 and 34.
	Land, mountainous.
	Soil, sandy and rocky, 2nd rate.
	Timber, fir, pine and cedar.
	Undergrowth, huckleberry and vine maple,