

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 29 S., R. 3 E.

CHAINS	<p>A Hemlock, 10 ins. in diam., bears S.15$\frac{1}{2}$*E., 46 lks. dist., marked $\frac{1}{4}$ S 22 B T.</p> <p>Asc. 145 ft. over NE. slope.</p> <p>46.75 Spur, slopes N., desc. 40 ft. over NW. slope.</p> <p>50.30 Draw, drains, N., asc. 340 ft. over broken NE. slope.</p> <p>57.60 Spring branch, 3 lks. wide, course NE., continue asc.</p> <p>74.70 Ridge, bears NW. and SE., desc. 120 ft. over W. slope to sec. cor.</p> <p>77.45 Forest Service Trail, bears N. and S.</p> <p>80.10 The cor. of secs. 15, 16, 21 and 22.</p> <p>Land, mountainous.</p> <p>Soil, gravelly and rocky, 3rd rate.</p> <p>Timber, fir, pine, hemlock and larch.</p> <p>Undergrowth, huckleberry, small fir and pine.</p>
	<p>N.0*02'W., bet. secs. 15 and 16.</p> <p>Over mountainous land, through medium timber and light undergrowth.</p> <p>Asc. 160 ft. over SW. slope.</p> <p>8.05 Forest Service Trail, bears NW. and SE. and ridge, bears same as the trail, desc. 135 ft. over NE. slope.</p> <p>16.45 Foot of desc. on E. slope, asc. 395 ft. over broken SE. slope to</p> <p>40.00 Set an iron post, 3 ft. long, 1 in. in diam., 28 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked</p> <p style="text-align: center;">S 16 S 15 1927</p> <p>from which</p> <p>A Larch, 10 ins. in diam., bears N.43*E., 16 lks. dist., marked $\frac{1}{4}$ S 15 B T.</p> <p>A Fir, 24 ins. in diam., bears S.75*W., 5 lks. dist., marked $\frac{1}{4}$ S 16 B T.</p> <p>Asc. 205 ft. over rocky SE. slope.</p> <p>52.20 Ridge, bears SW. and N., desc. 355 ft. along the top of the ridge.</p>