

County Surveyor's Record, Douglas County, Oregon

T. 29 S., R. 3 E., --- Meanders of sec. 6., continued.

CHAINS		
S.35*E.,	2.60 chs.	
S.12 $\frac{1}{4}$ *W.,	2.60 "	
S.24 $\frac{1}{4}$ *W.,	2.40 "	
S.82 $\frac{1}{2}$ *E.,	4.00 "	
S.47 $\frac{1}{2}$ *E.,	1.50 "	
S.38*E.,	3.60 "	Along steep rocky shore.
N.75 $\frac{1}{4}$ *E.,	5.10 "	
N.47*E.,	0.50 "	Leave rocks.
N.76 $\frac{1}{2}$ *E.,	0.80 "	
East,	3.95 "	
N.75*E.,	1.10 "	
N.84-3/4*E.,	3.60 "	
N.39-3/4*E.,	0.90 "	
N.21 $\frac{1}{4}$ *E.,	1.20 "	
N.3 $\frac{1}{2}$ *E.,	1.20 "	
N.20 $\frac{1}{2}$ *E.,	1.30 "	
N.35 $\frac{1}{2}$ *E.,	1.00 "	
N.71 $\frac{1}{2}$ *E.,	1.50 "	
S.86 $\frac{1}{2}$ *E.,	3.40 "	
S.66*E.,	2.30 "	
S.44*E.,	1.22 "	To meander cor. of secs.5 and 6, on S. shore of the lake.

Land, level and mountainous.

Soil, sandy, gravelly and rocky, 2nd and 3rd rate.

Timber, fir, pine and cedar.

Undergrowth, willow, alder, small fir, yew and pine.

GENERAL DESCRIPTION

The surface of this Township is mountainous and rough, ranging in elevation from 3,000 to 6,000 ft. above sea level.

The drainage is into the Umpqua and Rogue rivers. The divide between these two rivers extends through the Township from $\frac{1}{2}$ mile west of the NE. corner to 2 miles