

County Surveyor's Record, Douglas County, Oregon

Retracement and Dependent Resurvey
of Portion of Subdivisional Lines in T. 30 S., R. 1 W.

CHAINS

At exact corner point

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in ground, for $\frac{1}{4}$ sec. cor. of original sec. 13, with brass cap marked

$\frac{1}{4}$ S13 |
 1923

from which

A fir, 24 ins. diam., bears S.66*W., 63 lks. dist.

Marked $\frac{1}{4}$ S 13 B T. new B. T.

A fir, 40 ins. diam., bears N.49*W., 29 lks. dist.

Marked $\frac{1}{4}$ S 13 B T. new B. T.

The marks are overgrown on the old bearing tree intended in the original survey to refer to sec. 18, T. 30 S., R. 1 E.

Retracement

Thence

South, retracing old E. bdy. of sec. 13.

Descend 625 ft. over SE. slope.

5.51 Creek, 6 lks. wide, course SE.

24.90 Same creek, 6 lks. wide, course SW.

27.13 Same creek, 8 lks. wide, course SE.

32.77 Right bank of south fork of South Umpqua River, 50 lks. wide, course W.

Ascend 210 ft. over N. slope.

40.27 Fall 121 lks. W. of the cor. established by Hathorn as the cor. of secs. 13, 18, 19 and 24, located by measurement from the original bearing trees which are in agreement with the field notes, except that the NE. tree bears N.31*E., instead of N.47*E., as reported. The SE. and NW. trees are dead.

At exact corner point

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in ground, for SE. cor. of original sec. 13, with brass cap marked