

County Surveyor's Record, Douglas County, Oregon

61

Subdivision of T, 30 S., R. 1 E.

CHAINS

A fir, 20 ins. diam., bears N.26*E., 64 lks. dist.

Marked T 30 S R 1 E S 8 B T.

A fir, 18 ins. diam., bears S.59*E., 83 lks. dist.

Marked T 30 S R 1 E S 17 B T.

A cedar, 20 ins. diam., bears S.29*W., 101 lks. dist.

Marked T 30 S R 1 E S 18 B T.

A black oak; 12 ins. diam., bears N.3*W., 90 lks. dist.

Marked T 30 S R 1 E S 7 B T.

Land, mountainous.

Soil, clay loam, stony in places; 2nd. and 3rd. rate.

Timber, fir, hemlock, pine, and cedar.

Undergrowth, snowbrush, chinquapin, laurel, hazel, and lilac.

N.89*52'E., on a random line, bet. secs. 8 and 17.

40.00 Set temp. $\frac{1}{4}$ sec. cor.

80.16 Intersect N. and S. line, 19 lks. N. of the cor. of secs. 8, 9, 16, and 17.

Thence

West, on a true line, bet. secs. 8 and 17.

Over mountainous land, through heavy timber and dense undergrowth.

Ascend 50 ft. over SE. slope.

6.00 Spur, slopes SW., descend 360 ft. over W. slope.

16.05 Deep Cut Creek, 14 lks. wide, course SW., ascend 460 ft. over E. slope.

33.20 Summit of spur, slopes SE. A trail, bears NW. and SE. Descend gradually.

40.08 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked

S8
 $\frac{1}{4}$ —
 S17
 1923