

Township 30 South, Range 3 East,
Retracement of West Boundary

CHAINS

4.54 chs. dist., therefore the line between Tps. 30 S. Rs., 2 and 3 E, was erroneously established by Mr. Mensch and is out of position, necessitating a resurvey thereof.

From the cor. of Tps. 30 and 31 S., Rs. 2 and 3 E. North, on a random line, bet. Rs. 2 and 3 E., setting temp. $\frac{1}{4}$ Sec. cor. and Sec. cors. alternately at intervals of 40.00 chs.

472.27 Intersect N. Bdy. of T. 30 S., R. 2 E. 1.82 chs. West of the cor. of Tps. 29 and 30 S., Rs. 2 and 3 E. The bearing and length of this line is N.0°13'E., 472.27 chs.

Resurvey of South Boundary

From the cor. of Tps. 30 and 31 S., Rs. 3 and 4 E., which is a decayed pumice stone, 10x10x8 ins., loosely set, with no visible marking. In place of which Set an iron post, 3 ft. long, 3 ins. diam., 26 ins. in the ground, with brass cap marked

T 30 S
R 3 E R 4 E
S 30 S 31
S 1 S 6
T 31 S
1927

from which

A Red Fir, (orig.) 60 ins. diam., bears N.62°E., 49 lks. dist., mkd. T 30 S R 4 E S 31 B T.

A Red Fir, (orig.) dead, 50 ins. diam., bears S.30°E., 47 lks. dist., with traces of original marking.

A White Fir, (new) 12 ins. diam., bears S.79°E., 20 lks. dist., marked T 31 S R 4 E S 6 B T.