

6  
County Surveyor's Record, Douglas County, Oregon

Township 30 South, Range 3 East.  
Resurvey of South Boundary.

CHAINS	<p>Undergrowth, Snow Brush, Hazel, small Fir and Pine.</p> <hr/> <p>S.89*28'W., bet. Secs. 2 and 35.</p> <p>Over rolling land, through scattering timber and dense undergrowth.</p> <p>36.80 Middle of Union Creek, 50 lks. wide, Course SW., asc. slightly.</p> <p>39.44 Point 40.00 chs. in Westing from SE. cor. of Sec. 35. Set an iron post, 3 ft. long, 1 in. diam., 33 ins. in the ground, for <math>\frac{1}{4}</math> sec. cor. of Sec. 35 only, with brass cap mkd.</p> <p style="text-align: center;"><math>\frac{1}{4}</math> S 35 1927</p> <p>from which</p> <p style="padding-left: 40px;">A Hemlock, 9 ins. diam., bears N.55*E., 31 lks. dist., mkd. <math>\frac{1}{4}</math> S 35 B T.</p> <p style="padding-left: 40px;">A Fir, 20 ins. diam., bears N.70*W., 26 lks. dist., mkd. <math>\frac{1}{4}</math> S 35 B T.</p> <p>40.30 The <math>\frac{1}{4}</math> sec. cor. established for Secs. 2 and 35, which is an unmarked pumice stone, 10x10x6 ins. loosely set. In place of which</p> <p>Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for <math>\frac{1}{4}</math> sec. cor. of Sec. 2 only, with brass cap mkd.</p> <p style="text-align: center;"><hr/><math>\frac{1}{4}</math> S 2 1927</p> <p>from which</p> <p style="padding-left: 40px;">A Fir, (new) 12 ins. diam., bears S.36*E., 51 lks. dist., mkd. <math>\frac{1}{4}</math> S 2 B T.</p> <p style="padding-left: 40px;">A Fir, (orig.) 7 ins. diam., bears S.16<math>\frac{1}{2}</math>*W., 20 lks. dist., mkd. <math>\frac{1}{4}</math> S 2 B T.</p> <p style="padding-left: 40px;">A Cedar, (orig.) 10 ins. diam., bears N.54*W., 21 lks. dist., mkd. <math>\frac{1}{4}</math> S 35 B T. Obliterated.</p> <p>Thence</p> <p>S.88*58'W.,</p> <p>32.50 Enter Crater Lake Highway, bears N.80*E. and S.80*W.</p>
--------	---