

38
County Surveyor's Record, Douglas County, Oregon

Township 30 South, Range 3 East.
Subdivision.

CHAINS

A pine, 20 ins. dia., bears N. 18*E., 106 lks.
dist., mkd. $\frac{1}{4}$ S 36 B T.

A pine, 12 ins. dia., bears S. 5 $\frac{1}{2}$ *W., 76 lks.
dist., mkd. $\frac{1}{4}$ S 35 B T.

Thence over nearly level land.

72.15 Middle of the Crater Lake Highway, bears NE. and SW.

76.00 Asc. 20 ft. over SE. slope to

80.39 Intersect random sectional correction line, 4 lks. E.

to temp. cor. At point of intersection

Set an iron post, 3 ft. long, 2 ins. dia., 30 ins. in
the ground, for cor. of secs. 25, 26, 35, and 36,
with brass cap mkd.

T	30	S	R	3	E
	S	26	S	25	
	S	35	S	36	
					1927

from which

A pine, 8 ins. dia., bears N. 27*E., 32 lks.
dist., mkd. T 30 S R 3 E S 25 B T.

A pine, 14 ins. dia., bears S. 39*E., 19 lks.
dist., mkd. T 30 S R 3 E S 36 B T.

A pine, 9 ins. dia., bears S. 83*W., 51 lks.
dist., mkd. T 30 S R 3 E S 35 B T.

A fir, 5 ins. dia., bears N. 30*W., 31 lks.
dist., mkd. T 30 S R 3 E S 26 B T.

Land, level and rolling.

Soil, sandy and gravelly, 2nd rate.

Timber, pine, fir, and cedar.

Undergrowth, snow brush, hazel, small pine, fir, and
yew.

From the cor. of secs. 25, 30, 31, and 36, on E. bdy.
of Tp.

West, on true sectional correction line bet. secs.
25 and 36.