

47  
County Surveyor's Record, Douglas County, Oregon

Township 30 South, Range 3 East.  
Subdivision.

CHAINS

N. 0°1'W., bet. secs. 23 and 24.

Over rolling land, through light timber and medium undergrowth.

7.40 Diamond Lake Road, bears E. and W.

8.50 Desc. 75 ft. over NW. slope.

12.25 Left bank of the Rogue River, course W.

14.35 Right bank of the river; asc. 40 ft. over rolling SE. slope to  $\frac{1}{4}$  sec. cor., enter dense 2nd growth pine.40.00 Set an iron post, 3 ft. long, 1 in. dia., 30 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.
$$\begin{array}{c} \frac{1}{4} \\ \text{S } 23 \text{ | } \text{S } 24 \\ 1928 \end{array}$$

from which

A pine, 5 ins. dia., bears East, 9 lks. dist., mkd.  $\frac{1}{4}$  S 24 B T.A pine, 5 ins. dia., bears S. 51°W., 24 lks. dist., mkd.  $\frac{1}{4}$  S 23 B T.

Thence over nearly level land,

54.00 Enter heavy timber, bears NE. and SW.

62.00 Stock driveway, bears E. and W.

74.00 Leave timber, bears W. and NE.; enter swampy land, open grassy spaces, and patches of dense undergrowth.

80.00 Set an iron post, 3 ft. long, 2 ins. dia., 30 ins. in the ground, for, cor. of secs. 13, 14, 23, and 24, with brass cap mkd.

$$\begin{array}{c} \text{T } 30 \text{ S } \text{R } 3 \text{ E} \\ \text{S } 14 \text{ | } \text{S } 13 \\ \text{S } 23 \text{ | } \text{S } 24 \\ 1928 \end{array}$$

from which

A fir, 15 ins. dia., bears N. 3°45'E., 161 lks. dist., mkd. T 30 S R 3 E S 13 B T.

A pine, 32 ins. dia., bears S. 86°45'E., 313 lks. dist., mkd. T 30 S R 3 E S 24 B T.

A fir, 16 ins. dia., bears S. 88°W., 287 lks.