

County Surveyor's Record, Douglas County, Oregon

Township 30 South, Range 3 East.
Subdivision.

CHAINS

80.06 Intersect E. bdy. of Tp. 18 lks. S. of the cor. of
secs. 7, 12, 13, and 18.
Thence
S.89°46'W., on a true line.
Over rolling land, through heavy timber and light
undergrowth.
8.75 Stock trail, bears N. and SW.
14.00 Desc. 150 ft. over W. slope.
17.00 Foot of steep desc., enter river bottom and meadow,
bears N. and S.
27.75 Left bank of the Rogue River, course S.
29.55 Right bank of the river; asc. 50 ft. over E. slope
to $\frac{1}{4}$ sec. cor.
32.00 Forest Service Trail, bears N. and S.
40.03 Set an iron post, 3 ft. long, 1 in. dia., 30 ins. in
the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.
$$\begin{array}{r} S\ 12 \\ \hline S\ 13 \\ 1928 \end{array}$$

from which
A pine, 10 ins. dia., bears N. 73 $\frac{1}{2}$ °E., 75 lks.
dist., mkd. $\frac{1}{4}$ S 12 B T.
A pine, 8 ins. dia., bears S. 44°E., 51 lks.
dist., mkd. $\frac{1}{4}$ S 13 B T.
40.50 Spur, slopes SE.; desc. 20 ft. over SW. slope.
41.00 Creek, 8 lks. wide, course SE.; asc. 180 ft. over
broken NE. slope.
66.30 Spur, slopes SE.; desc. 25 ft. over SW. slope.
69.30 Spring branch, 1 lk. wide, course SE.; asc. 30 ft.
over E. slope to
80.06 The cor. of secs. 11, 12, 13, and 14.
Land, rolling and mountainous.
Soil, sandy, gravelly, and volcanic ash; 2nd rate.
Timber, fir, pine, hemlock, and cedar.
Undergrowth, vine maple, willow, huckleberry, small