

County Surveyor's Record, ⁵⁴Douglas County, Oregon

Township 30 South, Range 3 East.
Subdivision.

CHAINS	
	East. on a random line bet. secs. 23 and 26.
40.00	Set temp. $\frac{1}{4}$ sec. cor.
79.78	Intersect N. and S. line, 30 lks. S. of the cor. of secs. 23, 24, 25, and 26.
	Thence
	S.89*47'W., on a true line.
	Over mountainous land, through scattering timber and dense undergrowth.
	Desc. 85 ft. over W. slope.
1.66	Diamond Lake Road, bears N. and S.
3.00	Foot of steep desc.; thence over S. slope.
7.30	Asc. 40 ft. over SE. slope.
13.20	Spur, slopes S.; desc. 50 ft. over W slope.
19.40	Left bank of the Rogue River, course S.
21.10	Right bank of the river.
21.25	Brown's Cabin Road, bears N. and S.; enter a thick growth of small timber, asc. 275 ft. over NE. slope to
39.89	Set an iron post, 3 ft. long, 1 in. dia., 30 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\begin{array}{r} S\ 23 \\ \frac{1}{4} \\ \hline S\ 26 \\ 1928 \end{array}$
	from which
	A fir, 16 ins. dia., bears N. 32 $\frac{1}{2}$ *W., 32 lks. dist.; mkd. $\frac{1}{4}$ S 23 B T.
	A fir, 14 ins. dia., bears S. 61*E., 21 lks. dist.; mkd. $\frac{1}{4}$ S 26 B T.
	Asc. 785 ft. over broken NE. slope.
64.25	Rock ridge, bears N. and S.; enter very dense under- growth, desc. 340 ft. over SW. slope to
79.78	The cor. of secs. 22, 23, 26, and 27.
	Land, rolling and mountainous.
	Soil, sandy, gravelly, and rocky, 2nd and 3rd rate.
	Timber, fir, pine, and hemlock.
	Undergrowth, manzanita, rhodendron, chinquapin, willow,