


64
County Surveyor's Record, Douglas County, Oregon

Township 30 South, Range 3 East.
Subdivision.

CHAINS

over SE. slope.

75.75 Spur, slopes E.; desc. 80 ft. over NE. slope to
82.00 Intersect random sectional correction line 34 lks. E.
of temp. sec. cor. At this point
Set an iron post, 3 ft. long, 2 ins. dia., 32 ins. in
the ground, for cor. of Secs. 27, 28, 33 and 34,
with brass cap mkd.



from which

A Hemlock, 12 ins. dia., bears N.43*E., 37 lks.
dist., mkd. T 30 S R 3 E S 27 B T.

A Hemlock, 12 ins. dia., bears S.81*E., 26 lks.
dist., mkd. T 30 S R 3 E S 34 B T.

A Hemlock, 12 ins. dia., bears S.42*W., 36 lks.
dist., mkd. T 30 S R 3 E S 33 B T.

A Hemlock, 12 ins. dia., bears N.28*W., 82 lks.
dist., mkd. T 30 S R 3 E S 28 B T.

Land, mountainous.

Soil, sandy, gravelly and rocky, 3rd rate.

Timber, Fir, Pine and Hemlock.

Undergrowth, willow, vine maple, small fir and pine.

From the cor. of Secs. 26, 27, 34 and 35.

West, on true sectional correction line bet. Secs. 27
and 34.

Over mountainous land, through small timber and dense
undergrowth.

Desc. 650 ft. over broken SW. slope to

39.91 Set an iron post, 3 ft. long, 1 in. dia., 30 ins. in
the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

