

County Surveyor's Record, Douglas County, Oregon

Township 30 South, Range 3 East.
Subdivision.

CHAINS

Land, mountainous.

Soil, sandy, gravelly, and rocky, 3rd rate.

Timber, Fir, Pine and Hemlock.

Undergrowth, huckleberry, small fir and pine.

From the cor. of Secs. 32 and 33 only, on S. bdy. of
the Tp.

N.0°03'W., bet. Secs. 32 and 33.


Over mountainous land, through heavy timber and medium
undergrowth.

Desc. 190 ft. over broken NW. slope.

30.27 Spring branch, 1 lk. wide, Course W.; thence over W.
slope to

42.55 Point 40.00 chs. in Southing from the cor. of Secs.
28, 29, 32 and 33, determined as hereinafter
described. At this point

Set an iron post, 3 ft. long, 1 in. dia., 30 ins. in
the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.



from which

A Fir, 6 ins. dia., bears S.20°E., 22 lks.
dist., mkd. $\frac{1}{4}$ S 33 B T.

A Fir, 9 ins. dia., bears S.27°W., 34 lks.
dist., mkd. $\frac{1}{4}$ S 32 B T.

Asc. 25 ft. over SW. slope.

44.50 Spur, slopes W.; desc. 85 ft. over NW. slope.

51.00 Foot of desc. on W. slope; asc. 450 ft. over SW. and
S. slopes to Sec. cor.