

89
County Surveyor's Record, Douglas County, Oregon

11113

Township 30 South, Range 3 East.
Subdivision.

CHAINS

40.90 Spur, slopes W.; desc. 330 ft. over broken SW. slope to sec. cor.

63.50 Leave green timber; enter an old burn, dead standing and fallen timber, bears W. and SE.

72.42 The cor. of secs 4, 5, 8, and 9.

Land, mountainous.

Soil, sandy, gravelly, and rocky, 2nd rate.

Timber, fir and pine.

Undergrowth, vine maple, willow, huckleberry, small fir and pine.

From the cor. of secs. 31 and 32 only, on S. bdy of the Tp. hereinbefore described.

N. 0°04' W., bet. secs. 31 and 32.

Over mountainous land, through heavy timber and light undergrowth.

Over nearly flat top of a rock point, bearing NE.

0.40 Desc. cliff, 50 ft. high, bears NE. and SW.

1.00 Foot of cliff; desc. 105 ft. over NE. slope.

6.75 Wash, 5 lks. wide, course E.; asc. 535 ft. over S. slope.

27.90 Spur, slopes E.; desc. 145 ft. over NE. slope.

33.75 Draw, drains E.; asc. 115 ft. over S. slope.

37.25 Spur, slopes SE.; desc. 140 ft. over NE. slope to

43.29 Point 40.00 chs. in southing from the cor. of secs.

29, 30, 31, and 32, determined as hereinafter described. At this point

Set an iron post, 3 ft. long, 1 in. dia., 30 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

$\frac{1}{4}$
S 31 | S 32
1928

from which

A cedar, 20 ins. dia., bears N. 25° E., 31 lks.