

91
County Surveyor's Record, Douglas County, Oregon

11115

Township 30 South, Range 3 East.
Subdivision.

CHAINS	
	Over mountainous land, through heavy timber and medium undergrowth.
	Asc. slightly over S. slope.
2.00	Spur, slopes SW.; desc. 285 ft. over W. slope.
15.35	Draw, drains SW.; asc. slightly over S. slope.
18.00	Spur, slopes SW.; desc. 320 ft. over SW. slope.
40.04	Point for $\frac{1}{4}$ sec. cor. falls on 12 x 14 in. flat space, facing N., on a country rock ledge, forming the left bank of a creek. At this point Cut a cross(X) and $\frac{1}{4}$ below the cross, for $\frac{1}{4}$ sec. cor.; from which A Hemlock, 24 ins. dia., bears N.2*W., 88 lks. dist., mkd. $\frac{1}{4}$ S 29 B T. A Hemlock, 14 ins. dia., bears S.16*W., 72 lks. dist., mkd. $\frac{1}{4}$ S 32 B T.
40.09	Creek, 8 lks. wide, Course S.; asc. 780 ft. over broken NE. slope to
80.08	The cor. of Secs. 29, 30, 31 and 32. Land, mountainous. Soil, sandy, gravelly, and rocky, 3rd rate. Timber, Fir, Pine, Hemlock and Cedar. Undergrowth, huckleberry, rhododendron, willow, small fir and pine.

	West, on a True line bet. Secs. 30 and 31. Over mountainous land, through heavy timber and medium undergrowth. Asc. 750 ft. over E. slope.
31.20	Golden Stair Trail, bears N. and S.
33.75	Ridge, bears N. and S.; desc. 200 ft. over W. slope to
40.00	Set an iron post, 3 ft. long, 1 in. dia., 12 ^{ins.} / _{in} the ground, to bed rock, and build a mound of stone, 3 ft. base, 1 $\frac{1}{2}$ ft. high, around the post, for $\frac{1}{4}$ sec. cor., with brass cap mkd.