

102  
County Surveyor's Record, Douglas County, Oregon

Township 30 South, Range 3 East.  
Subdivision.

CHAINS

dist. from the cor. of secs. 12 and 13 only, and is hereinbefore described.

Land, mountainous.

Soil, sandy, gravelly, and rocky, 3 rd rate.

Timber, fir, pine, and hemlock.

Undergrowth, vine maple, snow brush, rhododendron, small fir, pine, and hemlock.

N.0°04'W., bet. secs. 7 and 8.


Over mountainous land, through heavy timber and dense undergrowth.

Asc. 170 ft. over S. slope.

7.00 Spur, slopes W.; desc. 35 ft. over NW. slope.

12.00 Draw, drains SW.; asc. 325 ft. over SW. slope to

40.00 Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap marked



from which


A fir, 26 ins. diam., bears N.5 $\frac{1}{2}$ °E., 141 lks. dist., marked  $\frac{1}{4}$  S 8 B T.

A fir, 36 ins. diam., bears N.28 $\frac{1}{2}$ °W., 152 lks. dist., marked  $\frac{1}{4}$  S 7 B T.

Asc. 75 ft. over SW. slope.

47.00 Spur, slopes W.; leave green timber, bears E. and W., enter an old burn, dead standing and fallen timber, desc. 410 ft. over broken NW. slope to

80.00 Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, for cor. of secs. 5, 6, 7, and 8, with brass cap marked



from which