

103
County Surveyor's Record, Douglas County, Oregon

11127

Township 30 South, Range 3 East.
Subdivision.

CHAINS

A fir, 36 ins. dia., bears N.0*45' E., 5.59 chs.
dist., mkd. T 30 S R 3 E S 5 B T.

A pine, 22 ins. dia., bears N. 6*30' W., 4.01 chs.
dist., mkd. T 30 S R 3 E S 6 B T.

No other trees available, build a mound of stone, 4 ft.
base, 2½ ft. high, 78 lks. West of the cor.

Land, mountainous.

Soil, sandy, gravelly, and rocky, 3rd rate.

Timber, fir, pine, and hemlock.

Undergrowth, vine maple, vines, weeds, grass, small
fir and pine.

N. 89*57' E., on a random line bet. secs. 5 and 8.

40.00 Set temp. ¼ sec. cor.

79.96 Intersect N. and S. line 14 lks. N. of the cor. of
secs. 4, 5, 8, and 9.

Thence

N. 89*57' W., on a true line.

Over mountainous land, through an old burn, dead timber,
and medium undergrowth.

Desc. 990 ft. over broken S W. slope.

34.15 Creek, 3 lks. wide, course SW.; asc. 100 ft. over
SE. slope, enter dense undergrowth.

37.50 Spur, slopes S; desc. 40 ft. over SW. slope to

39.98 Set an iron post, 3 ft. long, 1 in. dia., 28 ins. in
the ground, and build a mound of stone, 3 ft. base,
9 ins. high, around the post, for ¼ sec. cor., with
brass cap mkd.

¼ $\frac{S 5}{S 8}$
1928

from which

A dead cedar, 20 ins. dia., bears N. 77* E., 32
lks. dist., mkd. ¼ S 5 B T.