

Dependent Resurvey of Willamette Meridian  
through T. 31 S.

CHAINS

stone, firmly set, 4x8x8 ins. above ground, marked with  
3 notches on N. and S. edges; from which

A fir, 30 ins. diam., bears S.74\*W., 63 lks. dist.,  
marked T 31 S R 1 W S 24 B T (Old BT.)

The old bearing tree in sec. 13 is dead and fallen.

Re-mark the stone

S24 on SW. and

S13 on NW. face; from which

A fir, 30 ins. diam., bears N.77\*W., 29 lks. dist.,  
marked T 31 S R 1 W S 13 B T (New BT.)

Land, mountainous.

Soil, rocky; 4th rate.

Timber, fir, cedar, and yew.

Undergrowth, fir and vine maple.

North, on E. bdy. of sec. 13.

Over mountainous land, through heavy timber and dense  
undergrowth.

Desc. NE. slope.

8.23 Creek in rocky canyon, 4 lks. wide, course NW.

9.62 Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in  
the ground, for  $\frac{1}{4}$  sec. cor. of sec. 18, only, with  
brass cap marked

$\frac{1}{4}$  S 18

1923

from which

A hemlock, 5 ins. diam., bears N.43\*E., 18 lks. dist.,  
marked  $\frac{1}{4}$  S 18 B T.

A chinquapin, 5 ins. diam., bears S.71\*E., 37 lks.  
dist., marked  $\frac{1}{4}$  S 18 B T.

10.25 Recross same creek, 4 lks. wide, course NE.

12.10 Recross same creek, 4 lks. wide, course W., 209 ft. below  
sec. cor.

Asc. 320 ft. over SW. slope.