

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 31 S., R. 1 E.

CHAINS

Timber, fir, pine, and cedar.

Undergrowth, rhododendron, vine maple, hemlock, chinqua-
pin, and madrona.

N.0*03'W., bet. secs. 8 and 9.

Over mountainous land, through heavy timber and dense
undergrowth.

Descend 200 ft. over NW. slope to Beaver Creek.

12.74 Brook, 2 lks. wide, course NW.

20.09 Beaver Creek, 3 lks. wide, course W.

Foot of descent; ascend 280 ft. over SW. slope, to

40.00 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in
the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked

S8 | S9
1923

from which

A fir, 32 ins. diam., bears S.13*E., 30 lks. dist.,
marked $\frac{1}{4}$ S 9 B T.

A fir, 22 ins. diam., bears N.70*W., 13 lks. dist.,
marked $\frac{1}{4}$ S 8 B T.

Ascend 50 ft. to

50.00 spur, slopes W.; descend 100 ft. over NW. slope, to

58.68 Brook, 1 lk. wide, course SW.; ascend 220 ft. over SW.
slope, to

80.00 Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in
the ground, for cor. of secs. 4, 5, 8, and 9, with
brass cap marked

T31S | R1E
S5 | S4

S8 | S9
1923

from which

A cedar, 9 ins. diam., bears N.12*E., 19 lks. dist.,
marked T 31 S R 1 E S 4 B T.

A fir, 26 ins. diam., bears S.63*E., 45 lks. dist.,