

East Boundary, T. 31 S., R. 2 E.

CHAINS

to secs. 25, 36, 30 and 31 marked with 1 notch on S
and 5 notches on N face, from which

A White Fir, 24 ins. diam., bears N.32*W., 1 lk.
marked T 31 S R 2 E S 25 B T.

A Hemlock, 4 ins. diam., bears N.54 $\frac{1}{2}$ *E., 25 lks.
marked T 31 S R 3 E S 30 B T.

A White Fir, 10 ins. diam., bears S.19*W., 8 lks.
marked T 31 S R 2 E S 36 B T.

A White Fir, 24 ins. diam., bears S.20*E., 4 lks.
marked T 31 S R 3 E S 31 B T.

Land, broken and mountainous.

Soil, 2nd rate.

Timber, Fir and Pine.

Undergrowth, Vine Maple, Hazel and Young Fir.

Heavily timbered mountainous and dense underbrush.

80.00 chs.

July 29th, 1891.

North bet. secs. 25 and 30

Var.19*30'E.

- 3.00 A branch, 8 lks. wide, course SE ascend.
- 35.00 Summit of high rocky ridge. ± 500
- 40.00 Set stone, 20x20x10ins. for $\frac{1}{4}$ sec. cor. in mound of
stone on bedrock marked $\frac{1}{4}$ on West face, from which
A Pine, 20 ins. diam., bears S.17 $\frac{1}{2}$ *E., 65 lks.
marked $\frac{1}{4}$ S B T.
A Cedar, 6 ins. diam., bears N.50*W., 51 lks.
marked $\frac{1}{4}$ S B T.
- 44.50 Descend steep hill in heavy timber.
- 80.00 Set a Fir post, 4 ins. sq., 4 ft. long and 24 ins. in the
ground, for cor. to secs. 24, 25, 19 and 30 marked