

North Boundary, T. 31 S., R 2 E.

CHAINS		
	<p>A White Fir, 6 ins. diam., bears N.2*W., 39 lks. marked T 30 S R 2 E S 35 B T.</p> <p>A Red Fir, 8 ins. diam., bears S.39*W., 42 lks. marked T 31 S R 2 E S 2 B T.</p> <p>Land, broken.</p> <p>Soil, West part, 1st rate; East part, 2nd rate.</p> <p>Timber, Fir, Pine and Cedar.</p> <p>Undergrowth, Balm.</p> <p>Heavily timbered and mountainous.</p> <p style="text-align: right;">80.00 chs.</p>	
	<p>S.89*01'E., bet. secs. 1 and 36.</p> <p style="text-align: right;">Var.19*30'E.</p> <p>Descending rocky hill.</p>	
16.00	A branch, 5 lks. wide, course North.	- 100
40.00	<p>Set stone, 20x4x7 ins. 6 ins. deep in mound of stone, on bedrock for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on N. face, from which</p> <p>A Hemlock, 12 ins. diam., bears S.78*E., 22 lks. marked $\frac{1}{2}$ S B T.</p> <p>A Hemlock, 10 ins. diam., bears N.7*W., 27 lks. marked $\frac{1}{4}$ S B T.</p>	
46.25	A Creek, 6 lks. wide, course SE.	
54.25	Abbot Creek, 10 lks. wide, course South ascend steep hill.	
70.00	Top of ridge N. and S. Descend.	
80.00	<p>Cor. to Tps. 30 and 31 S., Rs2 and 3 E.</p> <p>Land, broken and mountainous.</p> <p>Soil, 2nd rate.</p> <p>Timber, Fir and Pine.</p> <p>Undergrowth, Vine Maple and Lilac.</p> <p>Heavily timbered and mountainous.</p> <p style="text-align: right;">80.00 chs.</p>	
	Aug. 4, 1891.	