

County Surveyor's Record, Douglas County, Oregon

11277

30

Subdivisions, T. 31 S., R. 2 E.

CHAINS

Set a post, 4 ins. sq., 3½ ft. long, 24 ins. in the ground, for ¼ Sec. Cor. marked ¼ S on N. face, from which

A Red Fir, 10 ins. diam., bears S.48*W., 29 lks. marked ½ S B T.

A Hemlock, 6 ins. diam., bears N.3*E., 4 lks. marked ¼ S B T.

Ascend steep mountain.

79.60 A point, about 1400 ft. above sec. cor. to secs. 26, 27, 34 and 35.

Land, mountainous.

Soil, 1st rate, for East; 40 chs. West; 40 chs. good.

Timber, Fir, Pine and Cedar.

Undergrowth, Vine Maple..

Heavily timbered and mountainous.

79.60 chs.

Sept. 9, 1891.

From the cor. to secs. 26, 27, 34 and 35.

I run

N.0*2*W., on true line bet. secs. 26 and 27.

Var.19*30'E.

Descending through heavy timber.

30.00 A spring, 1 lk. wide, course NE.

39.25 About 600 ft. below sec. cor. a branch, 4 lks. wide, course E.

40.00 Set a stone, 12x12x5 ins. 8 ins. in the ground, for ¼ sec. cor. marked ¼ on W face, from which

A White Fir, 12 ins. diam., bears S.52*W., 9 lks. marked ¼ S B T.

A Red Fir, 36 ins. diam., bears N.61*E., 39 lks. marked ¼ S B T.

73.00 A branch, 5 lks. wide, course S.80*E.