

Subdivisions, T. 31 S., R. 2 E.

CHAINS

A Red Fir, 24 ins. diam., bears N.80*W., 23 lks.
marked T 31 S R 2 E S 15 B T.

Land, broken and hilly.

Soil, 2nd rate.

Timber, Fir and Pine.

Undergrowth, Vine Maple and Lilac.

Heavily timbered.

80.00 chs.

Sept. 19, 1891.

S.89*57'E., on random bet. secs. 14 and 23.

Var. 19*E.

40.00 Set temporary $\frac{1}{4}$ S. cor.

79.80 Intersect N. and S. line 43 lks. South of cor. to secs.
13, 14, 23 and 24.

Thence I run

S.89*45'W., on true line bet. secs. 14 and 23.

Var. 19*30'E.

Through heavy Fir timber.

28.00 A creek, 10 lks. wide, course N.45*E.

39.90 A point, in a small creek, set a stone, 14x12x8 ins. in
mound of stone, on bedrock for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$
on N. face, from which

An Alder, 8 ins. diam., bears N.16*W., 26 lks.
marked $\frac{1}{4}$ S B T.

An Alder, 12 ins. diam., bears S.33*E., 39 lks.
marked $\frac{1}{4}$ S B T.

40.00 Leave creek course S.80*W.

46.00 A creek, 10 lks. wide, course S.40*E.

79.80 The cor. to secs. 14, 15, 22 and 23.

Land, rolling.

Soil, 2nd rate.