

Subdivisions, T. 31 S., R. 2 E.

CHAINS

- 2.50 Top of a ridge, 10 ft. high. Descend.
- 4.75 A branch, 2 lks. wide, course SE. Ascend.
- 5.00 Top of a ridge, E. and W. Descend.
- 19.25 A branch, 5 lks. wide, course SE. Ascend.
- 40.00 Set a stone, 24x14x8 ins. 6 ins. deep, on bedrock for
 $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on W. face, from which
 A Chinquapin, 10 ins. diam., bears S.59*W., 40 lks.
 marked $\frac{1}{4}$ S B T.
 A Silver Fir, 10 ins. diam., bears N.71*E., 10 lks.
 marked $\frac{1}{4}$ S B T.
- 42.00 A spring, course SE.
- 60.00 Top of a ridge, course E and W.
- 75.00 Descend into hollow.
- 80.00 A point, about level with cor. to secs. 10, 11, 14, and
 15.
 Set a stone, 12x10x5 ins. 8 ins. in the ground, for cor.
 to secs. 2, 3, 10 and 11 marked 5 notches on S and
 2 notches on E. edges, from which
 A Hemlock, 24 ins. diam., bears S.76*W., 64 lks.
 marked T 31 S R 2 E S 10 B T.
 A Red Fir, 36 ins. diam., bears N.22*W., 54 lks.
 marked T 31 S R 2 E S 3 B T.
 A Hemlock, 20 ins. diam., bears N.52*E., 78 lks.
 marked T 31 S R 2 E S 2 B T.
 A Hemlock, 14 ins. diam., bears S.71*E., 50 lks.
 marked T 31 S R 2 E S 11 B T.

Land, broken.

Soil, 2nd rate.

Timber, Fir and Pine.

Undergrowth, Vine Maple.

Heavily timbered.

80.00 chs.
 Sept. 22, 1891.

+ 100