

Subdivisions, T. 31 S., R. 2 E.

CHAINS

A White Fir, 18 ins. diam., bears S.24\*E., 53 lks.  
 marked T 31 S R 2 E S 28 B T.

A White Fir, 24 ins. diam., bears N.52\*E., 26 lks.  
 marked T 31 S R 2 E S 21 B T.

Land, South; gently rolling, North;  $\frac{1}{2}$  broken.  
 Soil, South;  $\frac{1}{2}$  1st rate, North;  $\frac{1}{2}$  2nd rate.  
 Undergrowth, Vine Maple.  
 Heavily timbered Fir and Pine.

80.00 chs.  
 Sept. 16, 1891.

S.89\*54'E., on random bet. secs. 21 and 28.  
 Var.19\*E.

40.00 Set temporary S cor.

79.90 Intersect N. and S. line 34 lks. N. of cor. to secs.  
 21, 22, 27 and 28.

Thence I run  
 N.89\*39'W., on true line bet. secs. 21 and 28.  
 Var.18\*E.

Descending steep hill in heavy Fir and Pine timber.

39.95 Set a stone, 12x12x8 ins. 8 ins. in the ground, for  $\frac{1}{4}$  + 700  
 sec. cor. marked  $\frac{1}{4}$  on N. face, from which  
 A White Fir, 24 ins. diam., bears S.27\*E., 15 lks.  
 marked  $\frac{1}{4}$  S B T.  
 A White Fir, 10 ins. diam., bears N.47\*E., 45 lks.  
 marked  $\frac{1}{2}$  S B T.

56.40 A branch, 2 lks. wide, course S.45\*W. + 1000

69.50 A branch, 14 lks. wide, course S.20\*W. Ascend.

79.90 The cor. to secs. 20, 21 28 and 29. + 800

Land, mountainous.  
 Soil, 2nd rate.  
 Timber, Fir and Pine