

Subdivisions, T. 31 S., R. 2 E.

CHAINS

N.0*4*W., on true line bet. secs. 17 and 18.

Var.19*E.

4.00 Elk Creek, 10 lks. wide, course West.

Ascend steep brushy hill.

20.00 Enter timber.

40.00 A point, about 500 ft. above sec. cor.

Set a stone, 16x12x5 ins. in mound of stone, on bedrock

for $\frac{1}{2}$ sec. cor. marked $\frac{1}{2}$ on W. face, from which

A Red Fir, 24 ins. diam., bears N.49*W., 84 lks.

marked $\frac{1}{2}$ S B T.

A Red Fir, 20 ins. diam., bears S.15*W., 52 lks.

marked $\frac{1}{2}$ S B T.

80.00 A point about 500 ft. above sec. cor.

Set a stone, 16x12x8 ins. 4 ins. in the ground, in mound

of stone, for cor. to secs. 7, 8, 17 and 18 marked

with 4 notches on S. and 5 notches on E. edges,

from which

A Red Fir, 8 ins. diam., bears S.32*E., 23 lks.

marked T 31 S R 2 E S 17 B T.

A White Fir, 24 ins. diam., bears N.10*E., 77 lks.

marked T 31 S R 2 E S 8 B T.

A Sugar Pine, 6 ins. diam., bears S.59*W., 30 lks.

marked T 31 S R 2 E S 18 B T.

A Red Fir, 12 ins. diam., bears N.54*W., 66 lks.

marked T 31 S R 2 E S 7 B T.

Land, broken and mountainous.

Soil, 2nd rate.

Timber, Fir and Pine.

Undergrowth, Lilac.

Heavily timbered.

Dense undergrowth, Lilac.

80.00 chs.
Sept. 30, 1891.