

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISION OF T. 24 S., R. 3 W.

CHAINS 19.00	A spring, flows NE.												
26.25	A branch, 1 lk. wide, course N. 60° E.; asc. 108 ft. over rolling NE. slope, changing to SE. slope.												
32.90	A spur ridge, bears N. 65° W. and N. 65° E.; asc. 26 ft. over broken S. slope.												
36.00	Same spur ridge, bears E. and W.; asc. 8 ft. over broken N. slope.												
38.75	<p>The cor. of secs. 19, 20, 29 and 30, remonumented by the county surveyor in 1928. when the original corner monumentation was intact, with a cedar post, 3½ ft. long, 5 ins. sq., firmly driven in the center of a decayed stump of the original hemlock corner tree, mkd. T 24 S 20 on NE., S 29 CS on SE., S 30 on SW., and R 3 W S 19 on NW. face, with 5 notches on E. and 2 notches on S. edge; from which I find only the remaining bearing trees mkd. by the county surveyor as follows:</p> <p style="margin-left: 40px;">A sawed fir stump, 32 ins. diam., bears S. 10½° E., 125 lks. dist., on which the scribe marks BT remain.</p> <p style="margin-left: 40px;">A fir, 32 ins. diam., bears S. 37° W., 161 lks. dist., mkd. on bark T 24 S R 3 W S 30 and mkd. BT. on almost healed blaze.</p> <p style="margin-left: 40px;">A cedar, 40 ins. diam., bears N. 75¼° W., 177 lks. dist., mkd. T 24 S R 3 W S 19 CS BT.</p> <p>At the corner point</p> <p>Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: auto;"> <tr> <td style="padding: 0 5px;">T 24</td> <td style="padding: 0 5px;">S R</td> <td style="padding: 0 5px;">3 W</td> </tr> <tr> <td style="padding: 0 5px;">S 19</td> <td style="border-left: 1px solid black; padding: 0 5px;">S 20</td> <td></td> </tr> <tr> <td style="padding: 0 5px;">S 30</td> <td style="border-left: 1px solid black; padding: 0 5px;">S 29</td> <td></td> </tr> <tr> <td colspan="3" style="padding: 0 5px;">1950</td> </tr> </table> </div> <p>from which</p> <p style="margin-left: 40px;">A fir, 6 ins. diam., bears N. 45½° E., 13 lks. dist., mkd. T 24 S R 3 W S 20 BT.</p> <p style="margin-left: 40px;">A fir, 6 ins. diam., bears S. 52° E., 44 lks. dist., mkd. T 24 S R 3 W S 29 BT.</p> <p style="margin-left: 40px;">Reset the county surveyor's wooden post inverted and alongside the iron post.</p> <p>Land, rolling and mountainous. Soil, heavy sandy clay loam. Timber, fir, hemlock, cedar, alder, maple, dogwood and madrona. Undergrowth, vinemaple, salmonberry, slickleaf, arrowwood, hazel, bracken, willow, thimbleberry and salal.</p>	T 24	S R	3 W	S 19	S 20		S 30	S 29		1950		
T 24	S R	3 W											
S 19	S 20												
S 30	S 29												
1950													
	<p>N. 72°14' W., bet. secs. 19 and 30.</p> <p>Asc. 4 ft. over NE. slope, through heavy timber and dense undergrowth.</p>												
0.30	Top of ascent on N. slope; desc. 123 ft. over NW. slope.												
3.85	A branch, 1 lk. wide, course N.; asc. 45 ft. over NE. slope.												
4.90	A spur, slopes N.; desc. 77 ft. over NW. slope.												
10.45	A branch, 4 lks. wide, course NE.; asc. 377 ft. over SE. slope.												
28.85	A spur, slopes S. 15° E.; desc. 38 ft. over SW. slope.												