

11558 County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the Sub. of T. 25 S., R. 3 W.

CHAINS	
	<p style="text-align: right;">from which</p> <p>A fir, 12 ins. diam., bears N.35°E., 41 lks. dist., with partial scribe marks visible on face of partially healed old blaze. (Old B.T.)</p> <p>A fir, 20 ins. diam., bears S.35°E., 30 lks. dist., with partial scribe marks visible on face of partially healed old blaze. (Old B.T.)</p> <p>A fir, 32 ins. diam., bears S.64°W., 14 lks. dist., with old blaze healed. (Old B.T.)</p> <p>A dead fir, 12 ins. diam., bears N.48°W., 34 lks. dist., mkd. T 25 R 3 S 15 B T. (Old B.T.)</p> <p>A fir, 20 ins. diam., bears N.20°W., 46 lks. dist., mkd. T 25 S R 3 W S 15 B T. (New B.T.)</p> <p>Land, mountainous. Soil, sandy loam and rocky clay; 2d and 3d rate. Timber, fir, hemlock, cedar, yew, pine, maple, and alder. Undergrowth, vinemaple, salal, salmonberry, rhododendron, bracken, willow, manzanita, slickleaf, and hazel.</p> <hr/> <p>From the cor. of secs. 13, 14, 23, and 24.</p> <p>N. 50° 49' W., bet. secs. 14 and 23.</p> <p>Asc. 358 ft. over SE. slope, changing to broken E. slope, through heavy timber and dense undergrowth.</p>
37.23	<p>Proportional measurement.</p> <p>Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.</p> <div style="text-align: center;"> $\frac{\frac{1}{4} \frac{S14}{S23}}{1943}$ </div> <p style="text-align: right;">from which</p> <p>A hemlock, 26 ins. diam., bears N.56$\frac{1}{2}$°E., 51 lks. dist., mkd. $\frac{1}{4}$ S 14 B T.</p> <p>A fir, 42 ins. diam., bears S.79°W., 315 lks. dist., mkd. $\frac{1}{4}$ S 23 B T.</p> <p>Asc. 369 ft. over broken SE. slope.</p>
37.88	A graded and graveled logging road, bears NE. and SW.
54.00	Head of ravine, course S.
59.50	A graded and graveled logging road, bears NE. and SW.
66.50	A trail and telephone line, bears N.60°E. and S.60°W.
67.60	A ridge, bears N.60°E. and S.60°W.; desc. 182 ft. over NW. slope.
74.46	<p>The cor. of secs. 14, 15, 22, and 23.</p> <p>Land, mountainous. Soil, sandy loam and rocky clay; 2d and 3d rate. Timber, fir, hemlock, cedar, maple, yew, alder, and pine. Undergrowth, vinemaple, salal, arrowwood, manzanita, hazel, bracken, slickleaf, willow, and huckleberry.</p> <hr/> <p>N. 2° 30' W., bet. secs. 14 and 15.</p> <p>Desc. 460 ft. over NW. slope, changing to NE. slope, through heavy timber and dense undergrowth.</p>
13.00	A graded and graveled logging road, bears NE. and SW.
21.10	A branch, 3 lks. wide, course NE.; desc. 244 ft. over broken NE. slope.