

Dependent Resurvey of the Sub. of T. 25 S., R. 3 W.

CHAINS	
	slope.
41.60	Top of ascent on S. slope; desc. 9 ft. over SW. slope.
44.00	Same branch, 5 lks. wide, course SE.; asc. 24 ft. over NE. slope.
46.80	The original $\frac{1}{4}$ sec. cor., the badly decayed point of a wooden stake on which only ax marks were found.
	At point for corner,
	Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with decayed remains of wooden stake deposited at the base, for $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4} \frac{S22}{S27}$ 1943
	from which
	A red cedar, 36 ins. diam., bears N.42°W., 19 lks. dist., with blaze healed. I re-blaze and re-mark this old bearing tree $\frac{1}{4}$ S 22 B T.
	A fir, 42 ins. diam., bears S.20°E., 16 lks. dist., mkd. on bark $\frac{1}{4}$ S B T. I re-blaze and re-mark this old bearing tree $\frac{1}{4}$ S 27 B T.
	Thence
	N. 89° 00' W., with new measurement.
	Asc. 263 ft. over broken E. slope.
22.00	A spur, slopes N.; desc. 30 ft. over NW. slope.
24.50	A branch, 2 lks. wide, course NE.; asc. 334 ft. over SE. slope.
46.14	The cor. of secs. 21, 22, 27, and 28.
	Land, mountainous.
	Soil, sandy loam and rocky clay; 2d and 3d rate.
	Timber, fir, hemlock, alder, cedar, maple, yew, pine, chinquapin, madrona, and dogwood.
	Undergrowth, vinemapple, salal, salmonberry, willow, hazel, bracken, arrowwood, manzanita, and slickleaf.
	N.9° 52' E., bet. secs. 21 and 22.
	Asc. 64 ft. over SE. slope, changing to broken E. slope, through heavy timber and dense undergrowth.
22.70	Top of ascent on E. slope; desc. 72 ft. over NE. slope.
29.45	A logging road, under construction, and saddle of ridge, bears NE. and S.15°W.; desc. 551 ft. over NW. slope.
50.65	A logging road, under construction, bears E. and W.
51.53	A shallow ravine, course NW.; asc. 5 ft. over SW. slope.
51.82	Proportional measurement.
	Set an iron post, 3 ft. long, 1 in. diam., 16 ins. in the ground to bedrock, and in a mound of stone to top, for $\frac{1}{4}$ sec. cor., with brass cap mkd.