

11572 County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the Sub. of T. 25 S., R. 3 W.

CHAINS
40.27

Proportional measurement.

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

$$\frac{1}{4} \frac{S10}{S15}$$

1943

from which

A fir, 54 ins. diam., bears N.2 $\frac{1}{2}$ °E., 74 lks. dist., mkd. $\frac{1}{4}$ S 10 B T.

A hemlock, 14 ins. diam., bears S.89°E., 50 lks. dist., mkd. $\frac{1}{4}$ S 15 B T.

Desc. 59 ft. over NW. slope.

43.30 A branch, 2 lks. wide, course N.; asc. 117 ft. over broken NE. slope.

52.70 A spur, slopes N.30°W.; desc. 159 ft. over SW. slope, changing to W. slope.

63.00 A branch, 4 lks. wide, course N.; asc. 83 ft. over NE. slope.

69.30 A spur, slopes N.; desc. 46 ft. over NW. slope.

80.54 The cor. of secs. 9, 10, 15, and 16.

Land, mountainous.
Soil, sandy loam and rocky clay; 2d and 3d rate.
Timber, fir, hemlock, alder, cedar, maple, yew, madrona, chinquapin, dogwood, and pine.
Undergrowth, vinemaple, salmonberry, huckleberry, bracken, hazel, willow, arrowwood, manzanita, and slickleaf.

N. 0° 12' E., bet. secs. 9 and 10.

Desc. 108 ft. over NW. slope, through heavy timber and dense undergrowth.

14.60 A branch, 15 lks. wide, course NE.; thence over broken E. slope.

28.80 A flat topped spur, slopes N. from S.15°W.; desc. 54 ft. over N. slope along top of spur.

40.72 Point for original $\frac{1}{4}$ sec. cor., determined by reference to the record bearing and distance from the old SE. bearing tree.

AT point for corner,

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

$$\frac{1}{4} \frac{S9}{S10}$$

1943

from which

A fir, 18 ins. diam., dead and down, bears S.55°E., 5 lks. dist., mkd. $\frac{1}{4}$ S B T. (Old B.T.)

A fir, 50 ins. diam., bears S.18 $\frac{1}{2}$ °E., 126 lks. dist., mkd. $\frac{1}{4}$ S 10 B T. (New B.T.)