

# 11594 County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of the Sub. of T. 25 S., R. 3 W.

CHAINS	
	dist., mkd. $\frac{1}{4}$ S 19 B T.
	A fir, 8 ins. diam., bears S.51°W, 18 lks. dist., mkd. $\frac{1}{4}$ S 30 B T.
40.20	Gassy Creek, 10 lks. wide, course NW.; asc. 59 ft. over SW. slope.
45.10	A spur, slopes S.; desc. 17 ft. over SE. slope.
46.40	A ravine, course S.; asc. 148 ft. over SW. slope.
49.70	A spring on line, flows SW.
56.00	A dim trail, bears N. and S.
60.30	A spur, slopes S.; desc. 16 ft. over SE. slope.
62.50	A branch, 6 lks. wide, course S.; asc. 40 ft. over SW. slope.
63.75	Foot of spur, slopes S.; desc. 3 ft. over SE. slope.
66.30	A branch, 6 lks. wide, course SW.; asc. 74 ft. over steep broken NW. slope near S. side of branch.
68.25	Same branch, 6 lks. wide, course N.85°W.; asc. 193 ft. over SW. slope.
81.28	The cor. of secs. 19, 20, 29, and 30.
	Land, mountainous, rolling mountainous, and level. Soil, sandy loam and rocky clay; 1st, 2d, and 3d rate. Timber, fir, hemlock, cedar, madrona, maple, alder, yew, chinquapin, pine, and dogwood. Undergrowth, vinemaple, salal, willow, arrowwood, hazel, bracken, poison oak, manzanita, slickleaf, salmonberry, thimbleberry, and syringa.
	N. 0° 07' W., bet. secs. 19 and 20.
	Asc. 1 ft. over SW. slope, through heavy timber and dense undergrowth.
0.70	A spur, slopes N.75°W.; desc. 77 ft. over NW. slope.
4.80	A branch, 5 lks. wide, course W.; asc. 142 ft. over SW. slope.
10.00	Aspur, slopes W.; desc. 51 ft. over NW. slope.
13.30	A branch, 3 lks. wide, course W.; asc. 210 ft. over broken S. slope, changing to SE. slope.
22.90	A dim trail, bears NE. and SW.
40.30	Top of spur ridge, bears E. and W.; desc. 5 ft. over rolling NE. slope.
42.08	Proportional measurement.
	Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.
	$\frac{1}{4}$ S19   S20 1944