

Retracement and Survey Portion South Bdy., T. 30 S., R. 7 W.

CHAINS

from which

A madrona, 10 ins. diam., bears N. 41° E., 71 lks. dist.,  
mkd. T 30 S R 7 W S 34 BT. (New B. T.)

A sugar pine, 20 ins. diam., bears S. 7° E., 59 lks. dist.,  
mkd. T 31 S R 7 W S 3 BT. (Old B. T.)

A madrona, 30 ins. diam., bears S. 13° W., 19 lks. dist.,  
mkd. T 31 S R 7 W S 4 BT. (Old B. T.)

A fir, 30 ins. diam., bears N. 47° W., 97 lks. dist.,  
mkd. T 30 S R 7 W S 33 BT. (Old B. T.)

Thence

West, retracing line bet. secs. 4 and 33.

Descend NW. slope.

2.00 Cow Creek, 175 lks. wide, course NE.; ascend.

4.55 Fence, bears N. and S.

5.22 Center of S. P. Ry. track, bears N. and S.

5.70 Fence, bears N. and S.

12.50 Top of spur, slopes SE.; descend.

14.60 Ravine, course SE.; ascend steep E. slope.

24.55 Top of point, slopes SW.; descend.

27.50 Ravine, course SW.; ascend.

30.10 Top of spur, slopes S.; descend.

34.35 Trail, bears NW. and SE.

36.30 Smith Creek, 8 lks. wide, course S. 60° E.

37.85 Creek, 1 lk. wide, course S. 20° E.; ascend E. slope.

39.37 Fall 54 lks. S. of the old  $\frac{1}{4}$  sec. cor., which is a badly decayed  
post, witnessed as described by the surveyor general. Alongside  
the old cor.

Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground,  
for  $\frac{1}{4}$  sec. cor. of sec. 33 only, with brass cap mkd.

$\frac{1}{4}$  S 33

1918

from which

A yellow pine, 24 ins. diam., bears N. 25° E., 22 lks. dist.,  
mkd.  $\frac{1}{4}$  S 33 BT.

A fir, 5 ins. diam., bears N. 44°30' W., 25 lks. dist.,  
mkd.  $\frac{1}{4}$  S 33 BT.

The true course and length of this line is N. 89°13' W., 39.37 chs.

Thence

S. 88°18' W., surveying the S. bdy. of sec. 33, counting distance  
from the sec. cor.

Ascend steep E. slope, through heavy timber and dense undergrowth.